TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT Dallas 123 Sample Rd 79001 **SCOPE OF INSPECTION** This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report. Α. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which В. was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. **The WDI** C. inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is D. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified E. expert THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any G. warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party. Н. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment. ı If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture Service of the Texas Department of Agriculture. 1A. Texas Maverick Inspection Company 1B. <u>654321</u> SPCS Business License Number Name of Inspection Company 1C. 220 Robertson Rd 79001 05 555-0404 Houston City Address of Inspection Company State Zip Telephone No. 1D. Ariel Esguerra Lic.110123 Name of Inspector (Please Print) 1E. Certified Applicator (check one) Technician 2. FHA 3. Wednesday, July 10, 2019 Case Number (VA/FHA/Other) Inspection Date 4A. Steve Joseph Seller □ Agent □ oxdot Management Co. oxdot Other oxdotName of Person Purchasing Inspection 4B. Seller Owner/Seller 4C. REPORT FORWARDED TO: Title Company or Mortgagee \square Purchaser of Service \square Seller ☑ Agent □ Buyer \square (Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy) The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Department of Agriculture Structural Pest Control Service. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected. 5. Residence, Detached garage List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection) Yes Nο 6A. Were any areas of the property obstructed or inaccessible? (Refer to Part B & C, Scope of Inspection) If "Yes" specify in 6B. 6B.The obstructed or inaccessible areas include but are not limited to the following: □ Insulated area of attic □ Plumbing Areas Planter box abutting structure \square Sub Floors П Slab Joints \square П Crawl Space abla \checkmark Soil Grade Too High Heavy Foliage Eaves Weepholes Other Specify : \square П 7A.Conditions conducive to wood destroying insect infestation: (Refer to Part J, Scope of Inspection) If "Yes" specify in 7B. Yes No 7B. Conducive Conditions include but are not limited to $\overline{\mathsf{V}}$ Wood to Ground Contact (G) Foamboards left in place (I) Excessive Moisture (J) П Debris under or around structure (K) Footing too low or soil line too high (L) \square Wood Rot (M) Heavy Foliage (N) Planter box abutting structure (O) Insufficient ventilation (T) Wooden Fence in Contact with the Structure (R) Wood Pile in Contact with Structure (Q) Other (C) Specify:

8G.Visible evidence of : Active sub-termites and previous sub- has been observed in the following areas : termites

No

No

No \square

No

 $\overline{\mathsf{V}}$

 \checkmark

 $\overline{\mathbf{V}}$

Active Infestation

Yes

Yes

Yes

Yes

Specify:

8F. Explanation of signs of previous treatment (including pesticides, baits, existing treatment stickers or other methods) identified:

If there is visible evidence of active or previous infestation, it must be noted. The type of insect(s) must be listed in the first blank and all identified infested areas of the property inspected must be noted in the second blank. (Refer to Part D, E & F, Scope of Inspection)

Previous Infestation

No

No

No

No

abla

 \checkmark

 $\overline{\mathsf{V}}$

Yes

Yes

Yes

Yes

8A.Subterranean Termites 8B.Drywood Termites

8E Other Wood Destroying Insects

Treatment sticker found on-site

8C.Formosan Termites

8D.Carpenter Ants

8.Inspection Reveals Visible Evidence in or on the structure:

 \checkmark

П

П

abla

Yes

Yes

Yes

Yes

TEXAS OFFICIAL WOOD DESTI	DOVING INSECT REPORT				Page 2 of 2
The conditions conducive to insect infestation reported in 7A & 7B: 9.Will be or has been mechanically corrected by inspecting company:	NOTING INSECT RELIGIO	Yes		No	
If "Yes," specify corrections: 9A.Corrective treatment recommended for active infestation or evidence of previous infestation as identified in Section 8. (Refer to Part G, H, and I, Scope of Inspection) 9B.A preventive treatment and/or correction of conducive conditions as identified in 7A & 7E Specify reason: Wood is conducive by design. Refer to Scope of Inspection Part J	•	Yes Yes	V	No No	
If treating for drywood termites or related insects, the treatment was: Full Carpent	Spot	□ Name of Pes	Other ticide, Bait o	□ or Other Me	thod
Diagram of Structure(s) Inspected The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by using the following codes: E- Evidence of Infestation, A-Active; P-Previous; D-Drywood Termites; S-Subterranean Termites; Fv-Formosan Termites; C-Conducive Conditions; B-Wood Boring Beetles; H- Carpenter Ants; Other(s) – Specify					
CARPENTER ANTS HERE	10.500	RPENTER TS HERE			
Neither I nor the company for which I am acting have had, presently have, or contemplate h which I am acting is associated in any way with any party to this transaction.	aving any interest in the property	v. I do further s	tate that ne	ther I nor th	ne company for
11Å. John Smith Lic.110123 12A. Inspector Approved: 11B. 123456 12B. Certified Applicator and Certified Applicator License Number	Inspection Was Posted At or Nea Electric Breaker Box Water Heater Closet Bath Trap Access Beneath the Kitchen Sink Date Posted 5/5/19	Date			
Statement of P I have received the original or a legible copy of this form. I have read and understand any re understand that my inspector may provide additional information as an addendum to this rep If additional information is attached, list number of pages : 2 Signature of Purchaser of Property or their Designee	commendations made. I have als	so read and u	nderstand th	e "Scope of	f Inspection." I
SPCS/T-4 (Rev. 09/01/07)					